

Fig. 1




Fig. 2




Fig. 3A

N	F <sub>1</sub>	F <sub>2</sub>	F <sub>3</sub>	F <sub>4</sub>	F <sub>5</sub>	F <sub>6</sub>
1	F	F	F	F	F	F

N	F <sub>T1</sub>	F <sub>T2</sub>	F <sub>T3</sub>	F <sub>T4</sub>	F <sub>T5</sub>	F <sub>T6</sub>	F <sub>T12</sub>	F <sub>T13</sub>	F <sub>T14</sub>	F <sub>T15</sub>	F <sub>T16</sub>	F <sub>T17</sub>
1	$\bar{F}$	$\bar{F}$	$\bar{F}$	$\bar{F}$	$\bar{F}$	$\bar{F}$	F	F	F	F	F	F

Fig. 3B




Fig. 4A

N	F <sub>1</sub>	F <sub>2</sub>	F <sub>3</sub>	F <sub>4</sub>	F <sub>5</sub>	F <sub>6</sub>
2	F	F	F	$\bar{F}$	$\bar{F}$	$\bar{F}$

N	F <sub>T2</sub>	F <sub>T4</sub>	F <sub>T6</sub>	F <sub>T7</sub>	F <sub>T9</sub>	F <sub>T11</sub>	F <sub>T13</sub>	F <sub>T15</sub>	F <sub>T17</sub>
2	$\bar{F}$	$\bar{F}$	$\bar{F}$	F	F	F	$\bar{F}$	$\bar{F}$	$\bar{F}$

Fig. 4B




Fig. 5A

N	F <sub>1</sub>	F <sub>2</sub>	F <sub>3</sub>	F <sub>4</sub>	F <sub>5</sub>	F <sub>6</sub>
3	F	F	$\bar{F}$	$\bar{F}$	F	F

N	F <sub>T2</sub>	F <sub>T4</sub>	F <sub>T7</sub>	F <sub>T8</sub>	F <sub>T10</sub>	F <sub>T11</sub>	F <sub>T15</sub>	F <sub>T17</sub>
3	$\bar{F}$	$\bar{F}$	F	$\bar{F}$	F	$\bar{F}$	F	F

Fig. 5B




Fig. 6







Fig. 7



*Fig. 8*



*Fig. 9*



*Fig. 10A*

$\left(\frac{V_{out}}{V_{dd}}\right)_{min}$	$\left(\frac{V_{out}}{V_{dd}}\right)_{max}$	$0_1$	$0_2$	$N_1$	$N_0$
1.3	1.5	0	0	0	1
1.5	2.0	1	0	1	0
2.0	3.3	1	1	1	1

*Fig. 10B*




Fig. 11




Fig. 12





Fig. 13



*Fig. 14*





Fig. 15

*Fig. 16*